2017 Cheap Safety Coverall Workwear Uniforms Working Coverall



Deatils:

- *two chest pockets
- *two leg pockets
- *two hip pockets
- *without belt and bukle

What is our quality control system?

1. Material inspection: All material will be inspected by our Q/C before or when porducing for all goods.

2. Production inspection: Our Q/C will inspect all production procedures and production reports will be issued and sent to you.

3. Product and packing inspection: Final inspection report will be issued and sent to you.

4. Shipment advice will be sent to customers with loading photos.